VISIBLE	MISSION NOTA	TIONS		7		
Inspector:	Same	N GORCIE				
Date of Ins	0///	page partico.				
Shift: 1st	Shift or LandSh		ne: 5AM	Comment	ts	
	Unite	Visual Minspection NORMAL				
		ABNORMAL				
<b>一位等的特別地域和澳洲</b>	nission From Shaker	M/M	MODERAL PROPERTY OF THE ANSWER OF THE ASSESSMENT			
Visible Em	ission From Conveyor System	None				
		110.0		1		

Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.

Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS		,	7			
Inspector: Alex Back	sty		_			
Date of Inspection:						
Shift: 1st Shift or 2nd Shift	Time:	4130m	nue ecokiams intellibriense discussivite Contention in			
Unite	Vastaāl Alaspecitoia:			(comments)	Tage Tage 22	
	<u>IAMARANI</u>					
	AMINIORIMAL				e zastilowa sii in	
Visible Emission From Shaker	NOR					
Visible Emission From Discharge			•			
Conveyor System	Nor					

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS			٦		
Inspector: Grange A Sance  Date of Inspection: 6/2/15  Shift: 1st Shift or 2nd Shift	e he z		_		
Date of Inspection: $6/2/15$					
Shift: 1st Shift or 2nd Shift	Time:	5:00 Am			
Unite	Visual Uniquestion Uniquestion			(Comments)	
	O) ABNORWAL				
Visible Emission From Shaker	Nor				
Visible Emission From Discharge Conveyor System	Non		•	<u> </u>	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS		٦			
Inspector: Paul Lank		_			
Date of Inspection:	5				
Shift: 1st Shift or 2nd Shift	Time:		Committed		
Units.	laualV iniciticeiqualla		(Oo)		
	<u>IPVARICI</u> II				
	MENGRIMAL			Andrews of the second s	
Visible Emission From Shaker	por			···	
Visible Emission From Discharge Conveyor System	201	•	<u> </u>		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EMISSION NOTATIONS			7		
Inspector: George It Same Date of Inspection: 6/3/15	/				
Date of Inspection: 6/3/15					
Shift: 1st Shift or 2nd Shi	₹ Time:	5-00 AM	The second of the second secon		
(Optic	Vistali Hispertinii			oompens	
Wale.	<u>Normacu</u> Gir				
	ABNORWAL				
Visible Emission From Shaker	Nor				
Visible Emission From Discharge Conveyor System	Nov		•		


- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to
  cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EMISSION NOTATIONS			٦		
Inspector: Alex Ba	HISH SR		-		·
Date of Inspection: Ce (3/			_		
Shift: 1st Shift or 2nd Shift	Time:	4:30m	and a supplication of the	THE CONTRACT OF THE PARTY OF TH	
(Unite	Visual Unboedioni			CANADAM SAINS	
	<u>informal</u> Of				
25.64	ABRORIMAL				
Visible Emission From Shaker	Nor				
Visible Emission From Discharge	Nove	**************************************	•		
Conveyor System	1/0/				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to
  cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.





- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS			٦		
Inspector: Alex B	active SR				
Date of Inspection:	115				
Shift: 1st Shift or 2nd Shift	Time:	5 pm	THE STANDARD SET OF THE ST		
(Oppie	VASGEAL		(CG	immiene	
	LEVERTORI				
	oj Abnorival				
Visible Emission From Shaker	Nos				
Visible Emission From Discharge		**Anne manufacture and the second	-		
Conveyor System	Nove	:		<u> </u>	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



Conveyor System

#### D.1.12 SDS I Daily Visible Emissions Notations Per Each Daylight Shift (Stack SDS 04)



VISIBLE EMISSION NOTATIONS Inspector: Date of Inspection: 500 Am Time: 2nd Shift 1st Shift or Shift: iligelaajaaja Natarakari Visible Emission From Shaker OCM & Visible Emission From Discharge Morma

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS			1	
Inspector: Alex Bas	tish SR.			
Date of Inspection: 6/5/15			-	
Shift: 1st Shift or 2nd Shift	Time:	C'our		
Unitic	Victorii เป็นสื่อยังเป็วที่เ			
	<u>llaminen</u>	1884 P		
	ABNORWAL			
Visible Emission From Shaker	NOR			
Visible Emission From Discharge			•	
Conveyor System	Nor			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS		- Control of the Cont	7		
Inspector: Lime M	Coecia		-		
Date of Inspection: $6/7/65$					
Shift: 1st Shift or 2nd Shift	Time:	SAIN			
Unite	Visteil Hisperdinii Normal			innicits	
	O) ABNORWAL				
Visible Emission From Shaker	NOR				
Visible Emission From Discharge Conveyor System	NOR	COMPANY OF THE PARTY OF THE PAR			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to
  cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS			1		
Inspector: Pan La					•
Date of Inspection:	15				
Shift: 1st Shift or 2nd Shift	Time:	5:00 DW		aments	
Unit	Vijelojel Nijelojelojeloje				
	<u>IMANIBIONI</u> Tor				
1000 m	<u>ABINIORUMAL</u>				
Visible Emission From Shaker	Nor				
Visible Emission From Discharge Conveyor System	NOT		•		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS			٦		
Inspector: Darren	B andjoe				
Date of Inspection:	-20 15		_		
Shift: 1st Shift or 2nd Shift	Timo:	(100pm		amients	
(Opplic	Visitel National	Table Same			
	<u>NORWAL</u>			No Mercent Commence	
	ABINORWAL,				
Visible Emission From Shaker	NOC			<u> </u>	
Visible Emission From Discharge Conveyor System	Noc				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS			7		
Inspector: Samian S	alinas Dr				
Date of Inspection: $6-8-15$			_		
Shift: 1st Shift or 2nd Shift	Time:	5:00Am	en en a Carlana est estatable : 12: Leadagh 18: Claris estat 18: Maria		
(Optič	in Visuali Historeculomi NokuMAL			comments all	
At the Francisco From Shaker	ABNORMAL				
Visible Emission From Shaker  Visible Emission From Discharge	1014	Camer'	•		
Conveyor System	1001				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to
  cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EMISSION NOTATIONS Inspector  U. J. J. J. J. J. J. J. C.	borg					
Date of Inspection: $(2 - 8 - 6)$	5		-			
Shift: 1st Shift or 2nd Shift	Time:	5°6m	and the second s			
Unite	Victorii Victoriani			inini Enter	(Tild)	
	<u>INORIMAL</u>					
	ABINIORMAL					ACCORDINATE DE LA CONTRACTOR DE LA CONTR
Visible Emission From Shaker	Normal					
Visible Emission From Discharge Conveyor System	Normal					

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS			7		
Inspector: Smell(0					
Date of Inspection: June 9.	15				
Shift: 1st Shift or 2nd Shift	Time:	530 AM			
Unitic .	Vigorija			kolmenstanlisi Li	
	<u>inormal</u>				
	AENTORVAL.				
Visible Emission From Shaker	nor				
Visible Emission From Discharge	nov				
Conveyor System	110.				 

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS			<del></del>		
Inspector:	n olpo	<			
Date of Inspection:	-2015				
Shift: 1st Shift or 2nd Shift	t Time:	6:00 pm		AND THE RESERVE OF THE PROPERTY OF THE PROPERT	
Ulijāta	vijstial Hitspaesitorii <u>Mohri Wall</u>			Commedia	
Visible Emission From Shaker	ABNIORNIAL.	<u>.</u>			
Visible Emission From Discharge Conveyor System	Nel		•		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS			٦		
Inspector: Part L	all				
Date of Inspection:	15				
Shift: 1st Shift or 2nd Shift	Time:	5:00 pm			
Ogiic	Vigual ไปเรื่อยอย่างที่			Commodates	
	NI ORRIMANE O) AGENTORIMANA				
Visible Emission From Shaker	V (0V	5.11.7.7.4.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.			
Visible Emission From Discharge Conveyor System	por				 

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS			<del></del> -		
Inspector: Smelko			-		
Date of Inspection: 6-10-19					
Shift: 1st Shift or 2nd Shift	Time:	5: AM			
Walte	vistorii) Unioreculiani			Commidity	
	INORMAL Vai				
	AMMINIMAL				
Visible Emission From Shaker	nor				 
Visible Emission From Discharge Conveyor System	nor	San Carlotte Control of the Ca			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS			<del>-</del> ,			
Inspector: Rubor A	John John John John John John John John	and the second				
Date of Inspection: 6-12-	-15					
Shift: 1st Shift or 2nd Shift	Time:	500p		maria-fra a 11. popularista i compropria dell'all'i i l'accidenti di dell'all'i i compropria dell'all'i compropria d		
Opiic	u v Vjetači. Unejoecuroni			ommiant)		
	<u>lavarioni</u>					
	<u>AMMARAAL</u>				ing and the second second second	
Visible Emission From Shaker	MM					
Visible Emission From Discharge Conveyor System	norm					

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

5 of 6

VISIBLE EMISSION NOTATIONS						
Inspector: Smell(0						
Date of Inspection: June 13	15					
Shift: 1st Shift or 2nd Shift	Time:	5100	All annual little and accompany to a self-or a self-or and			
Optic	Visional เป็นกรีกกระบบกับเกีย			(Colomienie)		
	<u>NORMAL</u> Or					
Visible Emission From Shaker	NOG		WHEN THE THE PARTY OF THE PROPERTY OF THE PROP		7.00	
Visible Emission From Discharge Conveyor System	MOR	- Particularies	•			


- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EMISSION NOTATIONS	A 6		1		
Inspector:	son Moken	did.			
Date of Inspection: (2-13-	15				
Shift: 1st Shift or 2nd Shift	Time:				
Unit	Visital Hijispieculpini NisiriMVIII Op			nentenus	
Visible Emission From Shaker	MONUM TABLES				
Visible Emission From Discharge Conveyor System	Norm				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.







VISIBLE EMISSION NOTATIONS						
Inspector: Danian Sal	inas Tr					
Date of Inspection:	5					
Shift: 1st Shift or Znd Shift	Time:	STOCKY	makale (Galoro Biliffica e 19/2 a anti Chiesa			
Unite	Visual Urspestioni			r Comments	THEY	
	OF ABNORMAL					
Visible Emission From Shaker	Nor	prom			,	
Visible Emission From Discharge Conveyor System	Nor					

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS			Ī			
Inspector:	, Aldams	Appendication and the second s				
Date of Inspection:	15					
Shift: (1st Shift) or 2nd Shift	Time:	5:000m	Confidence State Confid		F. Johnson v. Co.	
Unita	Visual Inspection NORMAL			Comments		
	or ABNORMAL					
Visible Emission From Shaker	Non				· ·	
Visible Emission From Discharge Conveyor System	Norm					

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EMISSION NOTATIONS				
Inspector: Smelko				
Date of Inspection: June 15	1			
Shift: 1st Shift or 2nd Shift		200 PM	. Comments	2000
Unit	Visual Inspection		Committee Co	Har service
	NORMAL			
	OF <u>ABNÖRMAL</u>			
Visible Emission From Shaker	noc	· ·		 
Visible Emission From Discharge	nor	ggggan. gggadise.		
Conveyor System	1 1			

Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.

Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.






VISIBLE EMISSION NOTATIONS Inspector: Date of Inspection: Time: 5:00 pm 1st Shift and Shift Shift: Comments Visual Unit Inspection NORMAL (0)7 ABNORMAL Nor Visible Emission From Shaker Visible Emission From Discharge Conveyor System

Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.

Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EMISSION NOTATIONS			<del></del> -		
Inspector: Sme 1100					
Date of Inspection: Tune 16,	15				
Shift: 1st Shift or 2nd Shift	Time:	5 PM			
Unite	Viguel Inspection I <u>NORIMAL</u> OI	i par		Comments.	
Visible Emission From Shaker	nor				
Visible Emission From Discharge Conveyor System	nor				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.





VISIBLE EMISSION NOTATIONS				
Inspector: George A	uncher			
Date of Inspection: (g/17/15)				
Shift: 1st Shift or 2nd Shift	Time:	5:00pm		
Unit	Visual Inspection <u>NORMAL</u> Or ABNORMAL		Comments	
Visible Emission From Shaker	Nor			
Visible Emission From Discharge Conveyor System	Nex			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

١	ISIBL	F.	FΝΛ	1221	ION	NOT	ΔΤΙ	NIS
v	IJIUL		LIVI	UUU	IOIV.	110	MIII	ノロコ

VISIBLE LIVIISSION NOTATIONS				
Inspector: Smelko				
Date of Inspection:	15			
Shift: (1st Shift) or 2nd Shif	Time:	5:00PM		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	nor			
Visible Emission From Discharge Conveyor System	nor			


- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



#### VISIBLE EMISSION NOTATIONS

Inspector: George A Sanch	rez			
Date of Inspection: 6/18/15				
Shift: 1st Shift or 2nd Shift	Time:	5:00 Am		
Unit.	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		pmments	
Visible Emission From Shaker	Nor			
Visible Emission From Discharge Conveyor System	Nor			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



#### VISIBLE EMISSION NOTATIONS

VISIBLE ENTISSION NOTATIONS				
Inspector: Smelto				
Date of Inspection: June 19	15			
Shift: 1st Shift or 2nd Shift	Time:	500		
Unit 1	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	noR			
Visible Emission From Discharge Conveyor System	nor			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

Non

VISIBL	$\Box$		ICC	IAOI	NO	ГΛТ	ION	C
AIZIBL	E	EIVI	122	ION.	NO	IAL	IUN	5

Visible Emission From Shaker

Conveyor System

Visible Emission From Discharge

Inspec	ctor:	rungel	sinher		
Date o	of Inspection:		untonia <sup>a</sup>		
Shift:	1st Shift	or 2nd Shi	Time:	2:00pm	
	Un		Visual Inspection NORMAL		Comments
			or <u>ABNORMAL</u>		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

VISIBLE	<b>EMISSION</b>	NOTATIONS

VIOLDEL LIVINGGIOTI TITO II TITOTI			i	
Inspector:	Nober			
Date of Inspection:	715			
Shift: (1st Shift) or 2nd Shif	t Time:	5:00pm	·	
Unit	Visual		Comments	
	Inspection NORMAL	ing fit to the second second second to the second second second second to the second second second second s		
	or <u>ABNORMAL</u>			
Visible Emission From Shaker	Norm			
Visible Emission From Discharge Conveyor System	Norm			


- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

#### **VISIBLE EMISSION NOTATIONS**

VIOLDED DIVISION THE TAXABLE			_		
Inspector: dime N C	palcia				
Date of Inspection:					
Shift: 1st Shift or Zhe Shi	t Time:	5			
Unit of the state	Visual Inspection <u>NORMAL</u> or ABNORMAL			Comments	
Visible Emission From Shaker	Non				
Visible Emission From Discharge Conveyor System	NOR			•	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



#### (Stack SDS 04)

#### VISIBLE EMISSION NOTATIONS

Inspector: Smello		, M.B.AULEL		
Date of Inspection: June 18.	15			
Shift: 1sk Shift or 2nd Shiff	Time:	6:30 pm		
	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	nor			
Visible Emission From Discharge Conveyor System	nor			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Revised 5/1/2015

(Stack SDS 04)

#### VISIBLE EMISSION NOTATIONS

Inspector: Smello			]	
Date of Inspection: June 18	15		7	
Shift: 1st Shift or 2nd Shiff	Time:	6.80 pm	-	
Unit h	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	nor			
Visible Emission From Discharge Conveyor System	nor			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

Inspector: George A Suncher	
Date of Inspection: 6/22/15	
Shift: 2st Shift or 2nd Shift	Time: 5:00 pm

Unit	Visual		Co	omments ' ' ' ''		ga Pilan
	Inspection .					
	<u>NORMAL</u>		Maria de la compania			$(x,y) \in \{x_1,x_2,\dots,x_n\}$
	or .					
	<u>ABNORMAL</u>					
Visible Emission From Shaker	4.7	AND THE RESERVE OF THE PROPERTY OF THE PROPERT			The state of the s	1888 - 1888 - 1888 - 1888 - 1888 - 1888 - 1888 - 1888 - 1888 - 1888 - 1888 - 1888 - 1888 - 1888 - 1888 - 1888
	Nar					
Visible Emission From Discharge						
Conveyor System	Nor					
hammen						

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.







#### VISIBLE EMISSION NOTATIONS

VIOLECE ENTISSION NO INTRODUCE				
Inspector: Smell C	)			
Date of Inspection: Jun 23,1	3			
Shift: 1st Shift or 2nd Shi	Time:	SAM		
Unit.	Visual Inspection NORMAL or ABNORMAL		omments	
Visible Emission From Shaker	nof			
Visible Emission From Discharge Conveyor System	nor	· · · · · · · · · · · · · · · · · · ·		

(Stack SDS 04)

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Revised 5/1/2015






(Stack SDS 04)

Inspector: George A Sunche	2				
Date of Inspection: 423/15			·		
Shift: 1st Shift or 2nd Shift	Time:	5:00 pm			
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comr	ments	
Visible Emission From Shaker	Ner				
Visible Emission From Discharge Conveyor System	Nor				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



#### VISIBLE EMISSION NOTATIONS

Visible Emission From Discharge

Conveyor System

BOD Nor

Inspector: Greenze Hou	nokor				
Date of Inspection: 6/24/15					
Shift: 1st Shift or 2nd Shift	Time:	5:00pm			
	Visual Inspection NORMAL or ABNORMAL		manus C	omments	
Visible Emission From Shaker	TO No				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

1131322 2111133131111311113111			_		
Inspector: Smello					
Date of Inspection: June 25	15				
Shift: 1st Shift or 2nd Shift	Time:	JOUAM			
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>			Comments	
Visible Emission From Shaker	nor	y APPERE			
Visible Emission From Discharge Conveyor System	nor	region .			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS			<del>-1</del>		
Inspector: George A Sam	hoz				
Date of Inspection: 6/25/15					
Shift: 1st Shift or 2nd Shift	Time: ¿	5:00 pm		a Caracana Anglesia ang Mi	
Unit	Visual Inspection <u>NORMAL</u> or ABNORMA <u>L</u>			Comments	
Visible Emission From Shaker	Nor				
Visible Emission From Discharge Conveyor System	Nor				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EMISSION NOTATIONS				
Inspector: Smelie				
Date of Inspection: June 98	,15			
Shift: 1st Shift or 2nd Shift	Time:	5:00		
Unit	Visual Inspection NORMAL or ABNORMAL		omments	
Visible Emission From Shaker	NOR	entropy .		
Visible Emission From Discharge	nor	No.		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

#### **VISIBLE EMISSION NOTATIONS**

Visible Emission From Discharge

Conveyor System

Wor

Nor

Inspector: Garge A. S Date of Inspection:	anchee			
Date of Inspection: 6/26/15				
Shift: 1st Shift or 2nd Shif	t Time:	5:00 pm		
Unit	Visual Inspection <u>NORMAL</u> or		Comments i	
Visible Emission From Shaker	ABNORMAL 2			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

Inspector: Smell	(O			
Date of Inspection:	27,15			
Shift: 1st Shift or 2nd Shift	t Time:	500Am		
Unit	Visual Inspection <u>NORMAL</u> or, <u>ABNORMAL</u>		Commer	
Visible Emission From Shaker	nor	etalianis.		
Visible Emission From Discharge Conveyor System	nor			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.





Inspector: Grosse A Some Date of Inspection:	ha				
Date of Inspection: 06/27/15					
Shift: 1st Shift or 2nd Shift	Time:	5:00 pm	-		
Unit and the second sec	Visual Inspection NORMAL or ABNORMAL			Comments	
Visible Emission From Shaker	Nor				
Visible Emission From Discharge Conveyor System	Nor			•	


- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



Visible Emission From Shaker


Conveyor System

Visible Emission From Discharge



VISIBLE EMISSION NOTATIONS			_		
Inspector: Sme	iko				
Date of Inspection: June 18	(5				
Shift: 1st Shift or 2nd Shift	Time: 5	1.00 Am			
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Co	mments	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



#### **VISIBLE EMISSION NOTATIONS**

Visible Emission From Discharge

Conveyor System

Nor

1,5,5,2,2,2,1,1,5,1,1,1,1,1,1,1,1,1,1,1,			<b>–</b>		
Date of Inspection: 6/28/15					
Date of Inspection: 6/28/15					
Shift: 2st Shift or 2nd Shift	t Time:	5:00 pm			
Unit s	Visual Inspection <u>NORMAL</u> or ABNORMAL		Com	ments	
Visible Emission From Shaker	Nor				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

Inspector: Smello				
Date of Inspection:	19,17			
Shift: 1st Shift or 2nd Shift	Time:	5AM		
Unit	Visual Inspection NORMAL or ABNORMAL		mments	
Visible Emission From Shaker	NOR	100000000000000000000000000000000000000		
Visible Emission From Discharge Conveyor System	noR	**Elizano.		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



(Stack SDS 04)

			_		
Date of Inspection: 6/24/15	er				
Date of Inspection: 6/24/15					
Shift: 1st Shift or 2nd Shift	Time:	Sicopr			
Unit	Visual			Comments	
	Inspection				A CHARLES AND THE STATE OF THE
	<u>NORMAL</u>	e sa di propinsi d			
	or				
	<u>ABNORMAL</u>				The state of the s
Visible Emission From Shaker	Nor				
Visible Emission From Discharge	4.2			-	
Conveyor System	Nor				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

VISI	BIF	FN	1ISSI	ON	TOM	TAT	IONS

			_		
Inspector: Smelko					
Date of Inspection:	15				
Shift: 1st Shift or 2nd Shift	Time:	5AM			
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comme	nts	
Visible Emission From Shaker	nor	.TTAKKina.			
Visible Emission From Discharge Conveyor System	nor	No.			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

#### VISIBLE EMISSION NOTATIONS

Inspector: Garse A Si	unchez				
Date of Inspection: . G/30			4		
Shift: (1st Shift) or 2nd Shift	Time:	5:00 pm	-		
Unit.	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>			Comments	
Visible Emission From Shaker	Nor	·			<u> </u>
Visible Emission From Discharge Conveyor System	Nor				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.